



**IRIS** instruments

## Syscal standard checklist

<b>Device</b>	
	Syscal standard (Tx and Rx fully charged)
	USB Cable with Syscal Plug
	Syscal user's manual
<b>Softs</b>	
	CD IRIS Instruments with USB Driver
	RES2/3DINV Dongle
	Laptop with Electre Pro + Prosys installed
<b>Accessories</b>	
	Battery chargers + adapters if necessary
	12V External Battery fully charged
	External Battery Cable (Red & Black)
	Alligator Clip (Red & Black)
	Stainless steel Electrodes or Unpolarizable Electrodes (3 + number of channels + extras)
	Cord Clip (3 + number of channels + extras)
	Reels of cable (3 + number of channels + extras)
	Measuring tape (non-metallic) or/and GPS
	Hammer
	Voltmeter with two 1m cables
	Salted water + bentonite